



Standard milling operation

Profile H, I, L


A




B




C




D




E




F




G




H




I




J




K




L



M




N




Hollow Section

O



P



R

